






# FRDM-KE02Z

I on ports ??? (IRQ on PTA5)



# FRDM-KE02Z40M

I on ports ??? (IRQ on PTA5)



# FRDM-KE04Z

I on ports ??? (IRQ on PTA5)

The SPI on the Master A layout does not match the MOSI and MISO pins

