





More functions available in the FRDM_TABLE_REV_x_x chart

FRDM-KE02Z



FRDM-KE02Z40M



FRDM-KE04Z

The SPI on the Master A layout does not match the MOSI and MISO pins

