



More functions available in the FRDM-TABLE\_REV\_x.x chart



# FRDM-KE02Z

1 on parts ???



# FRDM-KE02Z40M

1 on parts ???



# FRDM-KE04Z

The SPI on the Master A layout does not match the MOSI and MISO pins

1 on parts ???

